

Carney Consultancy Limited Risk Assessments & Method Statements

| C01 | Access Scaffold | C14 | Use of Push Along Vertical Lifts |
|-----|---|------|---|
| C02 | Flat Roof Work | C15 | Use of Stepladders |
| C03 | Fragile Roofs | C16 | Insulating a Roof Space and Pipe Work |
| C04 | Ladders | C17 | Removal and Fitting Fascia and Soffit Boards Non Asbestos |
| C05 | Material Hoists | C18 | Repair of Renewal of Gutters From Tower Scaffold Full Access Scaffolding |
| C06 | Mobile Elevated Working Platforms MEWPs | C18a | Installation of Gutters from Independent Scaffolding |
| C07 | Mobile Tower Scaffolds | C19 | Replace and Renew Flashing to Valley Gutter |
| C08 | Roof Truss Erection | C20 | Replace and Renew Times Slates to Pitched Roof |
| C09 | Roof Work Maintenance | C21 | Replacing Ridge Tiles |
| C10 | Sheeted Sloping Roods | C22 | Trestles Staging |
| C11 | Working at Height | C23 | Use of Safety Harnesses and Lanyards |
| C12 | Use of Hop Ups | C24 | Working Adjacent to Openings and Edges |
| C13 | Use of Podium Scaffolds | C25 | Working in Roof Spaces |